Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3578
Inspection Date: 2026-10-30
Inspection Outcome: Inspected

Inspection Comment:
WA# 12209- Oct. 30, 2026: 12:37 hrs. on site.

Wellhead: SCVA ball valve is found in the open position, CNRL is monitoring/reporting SCVF to standards.

Kermit last reported gas production rate: 2026-09 is in "Active Status".

Signage is compliant to standards.

Well Facility: Cata-Dyne regulator vent lines present. Service records inspected on site: orifice plate service record: 2026. CNRL to provide BCER inspector with most recent meter calibration record for the site.

Storage: double wall tanks (2x) on metal stand, grounded, and SDS labels posted.

Flowline: active flowline is connected to wellhead, well building, and not disconnected (isolated) to pipeline. Pig barrel chain attached to PAV (1x).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024958
Well ID: 12209
Well Name: CNRL HZ HELMET D- 018-A/094-P-08
Location: NTS: D- 018-A/094-P-08

Permit: 100039057
Pipeline Project ID: 000012317
Segment IDs (Location): 1 (From NTS: A- 098-L/094-P-01 To NTS: B- 026-D/094-P-08)

_____

Authorized by BCER