Inspection Report

Permit Holder: Trans Mountain Pipeline ULC
Inspection: 2026-3588
Inspection Date: 2026-10-15
Inspection Outcome: Inspected

Inspection Comment:
BCER conducted an inspection of Trans Mountain Pipeline ULC road and ancillary access infrastructure associated with AD 100101507. The inspection included Road 04618, Segments 238 and 242, as well as ancillary accesses 00171505, 00171507 and 00171510.

The inspection focused on the condition of the road segments and associated access infrastructure, including drainage, access control and the condition of the disturbed areas.

Inspected Road items:

* Road #04618 segment 238, kp998.100 road 3: reclaimed, access control in place. Road deactivated.
* Road #04618, segment 242, kp999.950: Access control present. Culverts removed and fully reclaimed. Water crossings reinstated using non-erodible material and flowing clean at time of inspection. Road deactivated.
* Road 6A kp1004.750. Road #04618, segment 251. Access control present, culverts removed and portions fully reclaimed. Road deactivated.

Inspected Ancillary Items:

* Road 10 reclamation - 1009.800. Access and stream crossings reclaimed. Vegetation throughout. Water crossings flowing clean at time of inspection.
* 1012.100 reclamation - Access reclaimed, no concerns. Access control in place. No BCER road permit associated with this section.
* 1012.500 reclamation - Road prism left in stable condition, culverts removed, berms in place and unused disturbed areas have been reclaimed. No BCER road permit associated with this section. All water crossings have been reinstated with suitable (non-erodible) creek bed material.
* 1013.300 reclamation - Road prism left in place. Access control present, culverts removed and water crossings reclaimed with suitable, non-erodible creek bed material. No BCER road permit associated with this area.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100101507
Road Number: 04618
Segment IDs (Location): 238 (From NTS: B- 018-H/092-H-11 To NTS: C- 008-H/092-H-11), 242 (From NTS: B- 020-H/092-H-11 To NTS: B- 020-H/092-H-11), 251 (From NTS: A- 085-B/092-H-11 To NTS: B- 094-B/092-H-11)

Permit: 100101507
AACT Number: 00171505
Site Type: Access

Permit: 100101507
AACT Number: 00171507
Site Type: Access

Permit: 100101507
AACT Number: 00171510
Site Type: Access

Permit Holder: Trans Mountain Pipeline ULC

_____

Authorized by BCER