Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3589
Inspection Date: 2026-10-28
Inspection Outcome: Inspected

Inspection Comment:
The gas lift metering building is complaint in its set up. No LELs.

Some observations;

The solar mast for the b-b-71-H is broken in half.

Check the bond and grounding wires on the sand filter catchment bin for the b-a-71-H well. The solar panel mast is loose for its sand filter skid and may be susceptible to damage.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100076979
Well ID: 28662
Well Name: PETRONAS HZ BEG B-A071-H/094-B-16
Location: NTS: B-A071-H/094-B-16

Permit: 100077205
Well ID: 28849
Well Name: PETRONAS HZ BEG B-B071-H/094-B-16
Location: NTS: B-B071-H/094-B-16

Permit: 100077595
Well ID: 29023
Well Name: PETRONAS HZ BEG B-C071-H/094-B-16
Location: NTS: B-C071-H/094-B-16

Permit: 100076979
Facility ID: 00025750
Facility Name: PETRONAS NORTHERNMONTNEY B-071-H/094-B-16 002
Facility Type: Well Facility
Location: NTS: B- 071-H/094-B-16

Permit: 100077205
Facility ID: 00025811
Facility Name: PETRONAS NORTHERNMONTNEY B-071-H/094-B-16 003
Facility Type: Well Facility
Location: NTS: B- 071-H/094-B-16

Permit: 100077595
Facility ID: 00025873
Facility Name: PETRONAS NORTHERNMONTNEY B-071-H/094-B-16 004
Facility Type: Well Facility
Location: NTS: B- 071-H/094-B-16

_____

Authorized by BCER