Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3597
Inspection Date: 2026-10-30
Inspection Outcome: Inspected

Inspection Comment:
This inspection is for the Gundy Trunk Road #2485 segment #1 and specifically for the bridge weight signs at approximately km 1.5. One sign is badly faded and should be replaced. Otherwise no concerns with road maintenance.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100078399
Road Number: 02485
Segment IDs (Location): 001 (From NTS: D- 095-I/094-B-09 To NTS: C- 095-I/094-B-09)

_____

Authorized by BCER