Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3604
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
ccess road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meets current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100064092
Well ID: 23953
Well Name: OVV ECOG HZ NOEL D- 024-K/093-P-01
Location: NTS: D- 024-K/093-P-01

Permit: 100064095
Well ID: 23963
Well Name: OVV ECOG HZ NOEL D-A024-K/093-P-01
Location: NTS: D-A024-K/093-P-01

Permit: 100064092
Facility ID: 00023409
Facility Name: OVV DEEPBASIN D-024-K/093-P-01 001
Facility Type: Well Facility
Location: NTS: D- 024-K/093-P-01

Permit: 100064095
Facility ID: 00023416
Facility Name: OVV DEEPBASIN D-024-K/093-P-01 002
Facility Type: Well Facility
Location: NTS: D- 024-K/093-P-01

_____

Authorized by BCER