Inspection Report

Permit Holder: Cardinal Energy Ltd.
Inspection: 2026-3607
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
Inspection Overview - Site 05-03-082-14 was inspected at approximately 1130 hours. Conditions were sunny, with a temperature of 6°C.
Inspection Results:
• Access and signage: Signage was clear and easy to read.

• Site condition: The wellsite was clean, with no vegetation-related concerns. Water pooling in corners berm break open in center back.

• Wellheads: Bull plugs, locks, and potential leaks were inspected. No SCV flow was detected, and all critical valves were locked. Signage and barricades in place. No concerns were identified.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100077789
Well ID: 29104
Well Name: CARDINAL MICA 05-03-082-14
Location: DLS: 05-03-082-14

Permit: 100077790
Well ID: 29105
Well Name: CARDINAL MICA A05-03-082-14
Location: DLS: A05-03-082-14

Permit: 100078109
Facility ID: 00007964
Facility Name: CARDINAL MICA 05-03-082-14 001
Facility Type: Satellite Battery
Location: DLS: 05-03-082-14

Permit Holder: Cardinal Energy Ltd.

Authorized by BCER