Inspection Report

Permit Holder: VERMILION ENERGY INC.
Inspection: 2026-3614
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
Inspection Overview - Site 12-06-081-13was inspected at approximately 1155 hours. Conditions were sunny, with a temperature of 6℃.

Inspection Results
• Access and signage: Signage was clear and easy to read.
• Site condition: The site is clean with two debris piles located right of the entrance. It is wet/ icy off the road and around all the equipment.
• Wellheads: Bull plugs, SCV, locks, and potential leaks were inspected. Was unable to reach the wellhead for an inspection - will follow up when conditions are more favorable/safer.
• Meter/separator buildings: Locks, leaks, caps, and vents were inspected. Operator contacted and confirmed fixes were completed on Nov 5. Part ordered for one item.
• Chemical tanks: Tanks were checked for leaks and inspected for proper grounding and secure caps. Visual from a distance found no concerns.
• Riser and pig stations: Chains and grounding were inspected. No concerns were identified.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100101212
Facility ID: 00026270
Facility Name: VERMILION DOE 12-06-081-13 001
Facility Type: Well Facility
Location: DLS: 12-06-081-13

Permit Holder: VERMILION ENERGY INC.

_____

Authorized by BCER