Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3619
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1100HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation & limited snow on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Well appears active. Barricades in place. Signage in place at entrance. Surface casing vent flow test- Minor Flow detected (unable to perform bubble test due to configuration of vent).

Meter building entry test- No alarms on personal monitor. No observed concerns at time of inspection.

Tanks and pump on site- No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100018421
Well ID: 09713
Well Name: CANLIN HZ LAPRISE A- 014-E/094-H-05
Location: NTS: A- 014-E/094-H-05

_____

Authorized by BCER