Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3620
Inspection Date: 2026-11-02
Inspection Outcome: Inspected

Inspection Comment:
* Travel to HZ SEPTIMUS G02-24-082-19, sign in site orientation
* meet with site supervisors, discuss operations.
* conduct site inspection, discuss inspection.
* review documents, discuss water permit.
* sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100117627
Well ID: 47898
Well Name: TOURMALINE HZ SEPTIMUS G02-24-082-19
Location: DLS: G02-24-082-19

_____

Authorized by BCER