Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3621
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

Inspection Comment:
* Travel to PETRONAS HZ BEG B-D059-I/094-B-16, sign in site orientation.
* meet with site supervisors. discuss operations review documents.
* review and discuss the B-059-I/094-B-16 Surface casing vent flow
* conduct site inspection, discuss inspection.
* sign out return to Dawson Creek

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100121761
Well ID: 56998
Well Name: PETRONAS HZ BEG B-B059-I/094-B-16
Location: NTS: B-B059-I/094-B-16

_____

Authorized by BCER