Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3629
Inspection Date: 2026-11-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1320HRS.

Access road- Vegetation & snow on access road. Frozen access. No concerns at the time of inspection.

Lease environment- Limited vegetation & snow on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Well appears active. Internal records indicate last production on March 2025. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Wellhead partially covered in insulated wrap. Surface casing vent flow test- No Flow detected.

Meter building entry test- LEL alarms on personal monitor. Vented building due to catadyne usage & retested- No Alarm on personal monitor. Calibration tags out of date (See attached). No concerns at time of inspection.

Chemical tanks and pump on site- No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100065468
Well ID: 24341
Well Name: SABA O&G ET AL LAPRISE D- 093-H/094-G-08
Location: NTS: D- 093-H/094-G-08

Permit: 100065468
Facility ID: 00023632
Facility Name: SABA O&G LAPRISECREEK D-093-H/094-G-08 001
Facility Type: Well Facility
Location: NTS: D- 093-H/094-G-08

Authorized by BCER