# Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3630
Inspection Date: 2026-11-03
Inspection Outcome: Inspected

**Inspection Comment:**
Officer Selected inspection of surface equipment on site.

Performed inspection of location at 1335HRS.

Access road- Snow on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation & limited snow on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100033380
Well ID: 14949
Well Name: CANLIN LAPRISE D- 094-H/094-G-08
Location: NTS: D- 094-H/094-G-08

_____

Authorized by BCER