Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3631
Inspection Date: 2026-11-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1418HRS.

Access road- Vegetation & snow on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation & snow on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Well appears inactive. Unable to retrieve production records from internal database. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Audible hissing coming from master valve handle. LEL alarm in proximity to wellhead. Surface casing vent flow test-Flow detected. Bubble test performed from 1421 to 1431- No observed bubbles.

Meter building entry test- No alarms on personal monitor. Calibration tags appear out of date. No other concerns at time of inspection.

Tanks on site- No concerns at time of inspection.

Additional Action Required

Please provide production records for the previous 14 months to compliance officer via email.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100005082
Well ID: 03633
Well Name: SABA O&G LAPRISE A- 042-H/094-G-08
Location: NTS: A- 042-H/094-G-08

_____

Authorized by BCER