Inspection Report

Permit Holder: Saba Oil & Gas Ltd.
Inspection: 2026-3633
Inspection Date: 2026-11-03
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1437HRS.

Access road- Vegetation & snow on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation & snow on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Well appears inactive. Internal records indicate well has not produced since March 2025. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Wellhead paritally covered in insulated wrap. Surface casing vent flow test-no flow detected.

Meter building entry test- No alarms on personal monitor. Calibration tags appear out of date. No other concerns at time of inspection.

Tanks and secondary containment on site-- Missing plug on drain outlet on secondary containment (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100046550
Well ID: 19107
Well Name: SABA O&G ET AL LAPRISE D- 032-H/094-G-08
Location: NTS: D- 032-H/094-G-08

_____

Authorized by BCER