Inspection Report

Permit Holder: NTE Energy Canada Ltd.
Inspection: 2026-3637
Inspection Date: 2026-11-09
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Nov. 10, 2026 - 11:08 hrs.

AD # 100034252 Project # 000010894 Segment # 3 (59.080905° / -121.685931°)

Flowline: Snake Wrap is hanging and detaching from flowlines: maintenance of plastic snake wrap may be required in the near future.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100034252
Pipeline Project ID: 000010894
Segment IDs (Location): 3 (From NTS: A- 098-B/094-P-04 To NTS: C- 095-B/094-P-04)

_____

Authorized by BCER