Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3643
Inspection Date: 2026-11-09
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1421HRS.

Access road- Snow accumulation on access road. No concerns at the time of inspection.

Lease environment- Limited snow and vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. ESD appears open. No barricades in place around wellhead (Limited risk due to isolated location). Signage in place at entrance. Wellhead partially covered in insulated wrap. Surface casing vent flow test-Flow detected. Performed bubble test from 1430 to 1440- No bubble observed.

Meter building entry test- No alarms on personal monitor. Meter calibration tags up to date (tag indicates 5 year exemption). No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038166
Well ID: 16322
Well Name: CNRL BEG D- 081-J/094-B-16
Location: NTS: D- 081-J/094-B-16

Permit: 100038166
Facility ID: 00020255
Facility Name: CNRL BEG D-081-J/094-B-16 001
Facility Type: Well Facility
Location: NTS: D- 081-J/094-B-16

Authorized by BCER