Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3649
Inspection Date: 2026-11-09
Inspection Outcome: Inspected

Inspection Comment:
WA#22878 and 22882 (A) Nov. 10, 2026: 12:37 hrs.

Abandoned Status: Wellheads have been removed (2x) both abandoned wells have been marked/signed (tombstone).

No invasive plants were observed on well pad at the time of inspection. No other issues noted with well location.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060304
Well ID: 22878
Well Name: CANLIN HZ YOYO A- 015-L/094-I-14
Location: NTS: A- 015-L/094-I-14

Permit: 100060306
Well ID: 22882
Well Name: CANLIN HZ YOYO A-A015-L/094-I-14
Location: NTS: A-A015-L/094-I-14

Permit: 100060306
Facility ID: 00022843
Facility Name: CANLIN YOYO A-015-L/094-I-14 001
Facility Type: Well Facility
Location: NTS: A- 015-L/094-I-14

_____

Authorized by BCER