Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3650
Inspection Date: 2026-11-09
Inspection Outcome: Inspected

Inspection Comment:
WA# 1313 - Nov. 10, 2026: 12:41 hrs. on site.

Wellhead: Abandoned status: no issues / concerns noted, client removed all associated wellhead structural materials/equipment and flowlines from site. Ground surface was leveled, remediated, and seeded.

Well Facility: Abandoned status: no issues / concerns noted: client removed all associated well facility structures/materials, chemical storage equipment, and flowlines from site.

No flowlines or pipelines are within pipeline pad/clearing area.

No invasive plants noted on site: Vegetative Cover = 95% herbaceous and 10% deciduous brush/browse species.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001721
Well ID: 01313
Well Name: CANLIN ET AL YOYO B- 024-L/094-I-14
Location: NTS: B- 024-L/094-I-14

Permit: 100001721
Facility ID: 00018501
Facility Name: CANLIN YOYO B-024-L/094-I-14 001
Facility Type: Well Facility
Location: NTS: B- 024-L/094-I-14

_____

Authorized by BCER