Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3651
Inspection Date: 2026-11-12
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 0920HRS.

Access road- Very muddy access road. No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Abandoned. Surface equipment removed from site.
Signage in place at lease entrance. Satellite battery active on site.
Building entry test- No alarms on personal monitor. No concerns at the time of inspection.

Water Injection building: Out of service.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006069
Well ID: 04287
Well Name: CNRL ET AL W EAGLE 06-07-085-18
Location: DLS: 06-07-085-18

Permit: 100010795
Facility ID: 00000382
Facility Name: CNRL EAGLE 06-07-085-18 001
Facility Type: Satellite Battery
Location: DLS: 06-07-085-18

_____

Authorized by BCER