Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-3652
Inspection Date: 2026-11-11
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1015HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Abandoned. Surface equipment removed from site. Signage in place at lease entrance. Internal records indicate facility (compressor, gas meter, separator) status is Active, however there is not equipment on site.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060948
Well ID: 23103
Well Name: STRATHCONA ET AL HZ SQUIRREL 07-33-087-19
Location: DLS: 07-33-087-19

Permit: 100060948
Facility ID: 00022957
Facility Name: STRATHCONA SQUIRREL 07-33-087-19 001
Facility Type: Well Facility
Location: DLS: 07-33-087-19

_____

Authorized by BCER