Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3654
Inspection Date: 2026-11-11
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1317HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment-Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place on well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Plug missing on needle valve on top of wellhead (See attached). Surface casing vent flow test- No Flow detected.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100013244
Well ID: 07787
Well Name: CNRL ET AL W STODDART 11-27-085-20
Location: DLS: 11-27-085-20

_____

Authorized by BCER