Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3658
Inspection Date: 2026-11-12
Inspection Outcome: Inspected

Inspection Comment:
Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations. Suspended well(s) conform to legislation.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100042048
Well ID: 17601
Well Name: OVV ECOG SWAN A- 017-G/093-P-09
Location: NTS: A- 017-G/093-P-09

Permit: 100065635
Well ID: 24478
Well Name: OVV ECOG HZ HERITAGE A-A017-G/093-P-09
Location: NTS: A-A017-G/093-P-09

Permit: 100065668
Well ID: 24484
Well Name: OVV ECOG HZ HERITAGE A-B017-G/093-P-09
Location: NTS: A-B017-G/093-P-09

Permit: 100067388
Well ID: 25157
Well Name: OVV ECOG HZ SWAN A-C017-G/093-P-09
Location: NTS: A-C017-G/093-P-09

Permit: 100067389
Well ID: 25159
Well Name: OVV ECOG HZ SWAN A-D017-G/093-P-09
Location: NTS: A-D017-G/093-P-09

Permit: 100042048
Facility ID: 00020616
Facility Name: OVV HERITAGE A-017-G/093-P-09 001
Facility Type: Well Facility
Location: NTS: A- 017-G/093-P-09

Permit: 100065635
Facility ID: 00023700
Facility Name: OVV HERITAGE A-017-G/093-P-09 003
Facility Type: Well Facility
Location: NTS: A- 017-G/093-P-09

Permit: 100065668
Facility ID: 00023702
Facility Name: OVV HERITAGE A-017-G/093-P-09 004
Facility Type: Well Facility
Location: NTS: A- 017-G/093-P-09

Permit: 100067388
Facility ID: 00024032
Facility Name: OVV HERITAGE A-017-G/093-P-09 007
Facility Type: Well Facility
Location: NTS: A- 017-G/093-P-09

Permit: 100067389
Facility ID: 00024033
Facility Name: OVV HERITAGE A-017-G/093-P-09 008
Facility Type: Well Facility
Location: NTS: A- 017-G/093-P-09

_____

Authorized by BCER