Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3659
Inspection Date: 2026-11-12
Inspection Outcome: Inspected

Inspection Comment:
Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations. Suspended well conforms to legislation.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048568
Well ID: 19650
Well Name: OVV ECOG SWAN A- 091-C/093-P-09
Location: NTS: A- 091-C/093-P-09

Permit: 100057136
Well ID: 22165
Well Name: OVV ECOG HZ SWAN D- 091-C/093-P-09
Location: NTS: D- 091-C/093-P-09

Permit: 100048568
Facility ID: 00021301
Facility Name: OVV HERITAGE A-091-C/093-P-09 001
Facility Type: Well Facility
Location: NTS: A- 091-C/093-P-09

Permit: 100057136
Facility ID: 00022539
Facility Name: OVV HERITAGE D-091-C/093-P-09 001
Facility Type: Well Facility
Location: NTS: D- 091-C/093-P-09

_____

Authorized by BCER