Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3660
Inspection Date: 2026-11-12
Inspection Outcome: Inspected

Inspection Comment:
Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

Note: Well identifier sign for A-B88-A well is on the ground and should be redisplayed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100063522
Well ID: 23729
Well Name: OVV ECOG HZ SWAN A- 088-A/093-P-09
Location: NTS: A- 088-A/093-P-09

Permit: 100063523
Well ID: 23730
Well Name: OVV ECOG HZ SWAN A-A088-A/093-P-09
Location: NTS: A-A088-A/093-P-09

Permit: 100063524
Well ID: 23731
Well Name: OVV ECOG HZ SWAN A-B088-A/093-P-09
Location: NTS: A-B088-A/093-P-09

Permit: 100063522
Facility ID: 00023287
Facility Name: OVV HERITAGE A-088-A/093-P-09 001
Facility Type: Well Facility
Location: NTS: A- 088-A/093-P-09

Permit: 100063523
Facility ID: 00023288
Facility Name: OVV HERITAGE A-088-A/093-P-09 002
Facility Type: Well Facility
Location: NTS: A- 088-A/093-P-09

Permit: 100063524
Facility ID: 00023289
Facility Name: OVV HERITAGE A-088-A/093-P-09 003
Facility Type: Well Facility
Location: NTS: A- 088-A/093-P-09

_____

Authorized by BCER