Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3661
Inspection Date: 2026-11-12
Inspection Outcome: Inspected

Inspection Comment:
Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations. Suspended well meets suspended legislation.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100046423
Well ID: 19142
Well Name: OVV SWAN A- 011-G/093-P-09
Location: NTS: A- 011-G/093-P-09

Permit: 100068708
Well ID: 25420
Well Name: OVV ECOG HZ SWAN D-A011-G/093-P-09
Location: NTS: D-A011-G/093-P-09

Permit: 100069267
Well ID: 25419
Well Name: OVV ECOG HZ SWAN D- 011-G/093-P-09
Location: NTS: D- 011-G/093-P-09

Permit: 100046423
Facility ID: 00021079
Facility Name: OVV HERITAGE A-011-G/093-P-09 001
Facility Type: Well Facility
Location: NTS: A- 011-G/093-P-09

Permit: 100068708
Facility ID: 00024141
Facility Name: OVV HERITAGE D-011-G/093-P-09 001
Facility Type: Well Facility
Location: NTS: D- 011-G/093-P-09

Permit: 100069267
Facility ID: 00024140
Facility Name: OVV HERITAGE D-011-G/093-P-09 002
Facility Type: Well Facility
Location: NTS: D- 011-G/093-P-09

_____

Authorized by BCER