Inspection Report

Permit Holder: Fireweed Energy Ltd.
Inspection: 2026-3663
Inspection Date: 2026-11-11
Inspection Outcome: Inspected

Inspection Comment:
COMMENTS:

-drove to location but found no well. There is a clearing approximately a normal 'lease size' that is covered in vegetation and has a windrow down the middle of 'lease' area.

-there is quite a bit of thistle present, and this should be dealt with by the Permit Holder, Fireweed Energy. Even with no well drilled, the Permit Holder is responsible for weed management on lease.

-No location signage present anywhere that is visible.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100119057
Well ID: 52548
Well Name: FIREWEED HZ FORTSTJOHNSE 01-11-083-17
Location: DLS: 01-11-083-17

_____

Authorized by BCER