Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3667
Inspection Date: 2026-11-11
Inspection Outcome: Inspected

Inspection Comment:
COMMENTS:

-abandoned well with all equipment remaining in place. Wellhead has been removed. Pipeline remains but is disconnected.

-there are 2 pipeline signs bent over to the ground and not legible at lease edge.

-location signage is lying on the ground beside the meter box with no symbols on it.

-meter box, piling, pipeline riser and propane tank remain in place.

-lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100044556
Well ID: 18589
Well Name: CNRL FLATROCK 04-19-084-16
Location: DLS: 04-19-084-16

Permit: 100044556
Facility ID: 00020914
Facility Name: CNRL FLATROCK 04-19-084-16 001
Facility Type: Well Facility
Location: DLS: 04-19-084-16

_____

Authorized by BCER