Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-3671
Inspection Date: 2026-11-11
Inspection Outcome: Inspected

Inspection Comment:
Inspection Overview

Site was inspected at approximately 0000 hours. Conditions were overcast with a temperature of 6°C.

Inspection Results
• Access and signage: Signage was clear and easy to read.
• Site condition: The wellsite was clean, with no vegetation-related concerns.
• Wellheads: Bull plugs, SCV, locks, and potential leaks were inspected. No SCV flow was detected, and all critical valves were locked. No concerns were identified.
• Meter/separator buildings: Locks, leaks, caps, and vents were inspected. No concerns were identified.
• Chemical tanks: Tanks were checked for leaks and inspected for proper grounding. No concerns were identified.
• Riser and pig stations: Chains and grounding were inspected. No concerns were identified.
• Associated pipelines: Vegetation cover along the pipelines was well established.
• Flare/ knockout: on/ lit.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100034605
Well ID: 15462
Well Name: ARCRES DAWSON 13-07-079-14
Location: DLS: 13-07-079-14

Permit: 100109374
Well ID: 40040
Well Name: ARCRES HZ DAWSONCREEK A13-07-079-14
Location: DLS: A13-07-079-14

Permit: 100110831
Well ID: 40658
Well Name: ARCRES HZ DAWSON CREEK B13-07-079-14
Location: DLS: B13-07-079-14

Permit: 100110831
Well ID: 40659
Well Name: ARCRES HZ DAWSON CREEK C13-07-079-14
Location: DLS: C13-07-079-14

Permit: 100110831
Well ID: 40660
Well Name: ARCRES HZ DAWSON CREEK D13-07-079-14
Location: DLS: D13-07-079-14

Permit: 100110831
Well ID: 40661
Well Name: ARCRES HZ DAWSON CREEK E13-07-079-14
Location: DLS: E13-07-079-14

Permit: 100110831
Well ID: 40662
Well Name: ARCRES HZ DAWSON CREEK F13-07-079-14
Location: DLS: F13-07-079-14

Permit: 100110831
Well ID: 40663
Well Name: ARCRES HZ DAWSON CREEK G13-07-079-14
Location: DLS: G13-07-079-14

Permit: 100110831
Well ID: 40664
Well Name: ARCRES HZ DAWSON CREEK H13-07-079-14
Location: DLS: H13-07-079-14

Permit: 100110831
Well ID: 40665
Well Name: ARCRES HZ DAWSON CREEK I13-07-079-14
Location: DLS: I13-07-079-14

Permit: 100110831
Well ID: 40666
Well Name: ARCRES HZ DAWSON CREEK J13-07-079-14
Location: DLS: J13-07-079-14

Permit: 100034605
Facility ID: 00020071
Facility Name: ARCRES DAWSON CREEK 13-07-079-14 001
Facility Type: Well Facility
Location: DLS: 13-07-079-14

Permit: 100071420
Pipeline Project ID: 000022084
Segment IDs (Location): 2 (From DLS: 13-07-079-14 To DLS: 09-17-079-14)

Permit Holder: ARC Resources Ltd.

_____

Authorized by BCER