Inspection Report

Permit Holder: Tidewater Midstream and Infrastructure Ltd.
Inspection: 2026-3698
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Access road poor, signage is present and lease is free of debris but is overgrown. ESD(s) and scv(s) at wellhead good. Chem tank(s) DW and pigging station(s) are good.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100062999
Well ID: 23654
Well Name: TIDEWATER KELLY D- 018-J/093-P-01
Location: NTS: D- 018-J/093-P-01

Permit: 100062999
Facility ID: 00023247
Facility Name: TIDEWATER KELLY D-018-J/093-P-01 001
Facility Type: Well Facility
Location: NTS: D- 018-J/093-P-01

_____

Authorized by BCER