Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-3709
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations.

Note: Chem Tank currently empty and secondary containment missing bull plug which needs to be replaced prior to filling chemical tank with product. Chem tank and containment have also been knocked off its wooden planking and should be assessed for stability prior to filling. Containment needs to be monitored to ensure no accidental release of untested water while plug is missing.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100032296
Well ID: 14727
Well Name: CVE ENERGY KELLY C- 017-G/093-P-01
Location: NTS: C- 017-G/093-P-01

_____

Authorized by BCER