Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3716
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048234
Well ID: 19434
Well Name: OVV KELLY D- 077-G/093-P-01
Location: NTS: D- 077-G/093-P-01

Permit: 100073482
Well ID: 27178
Well Name: OVV CRP HZ KELLY D-A077-G/093-P-01
Location: NTS: D-A077-G/093-P-01

Permit: 100048234
Facility ID: 00021190
Facility Name: OVV KELLY D-077-G/093-P-01 001
Facility Type: Well Facility
Location: NTS: D- 077-G/093-P-01

Permit: 100073482
Facility ID: 00025043
Facility Name: OVV KELLY D-077-G/093-P-01 003
Facility Type: Well Facility
Location: NTS: D- 077-G/093-P-01

_____

Authorized by BCER