Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3740
Inspection Date: 2026-11-17
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1216HRS.

Access road- No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Pumpjack & Wellhead Suspended. Barricades in place around wellhead. Signage in place at well partial obstruction due to it leaning forward against barricade (see attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected.

Building entry test- No alarms on personal monitor. Building appears out of service. Needle valve on flowline going into building has greasy like fluid coming from threaded connection and running down valve (see attached).

Tanks on site-No concerns at time of inspection. Appear out of service.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001237
Well ID: 00956
Well Name: CNRL ET AL W PEEJAY D- 054-G/094-A-15
Location: NTS: D- 054-G/094-A-15

Permit: 100010789
Facility ID: 00000376
Facility Name: CNRL PEEJAYWEST D-054-G/094-A-15 001
Facility Type: Satellite Battery
Location: NTS: D- 054-G/094-A-15

Authorized by BCER