Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3749
Inspection Date: 2026-11-19
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1310HRS.

Access road- Limited vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. No barricades in place around wellhead (Limited risk due to isolated location). Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected.

Building entry test- No alarms on personal monitor. Building appears out of service.

Tank on site- Appears out of service.

Note- Insulated wrap around wellhead decaying.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040368
Well ID: 17410
Well Name: CNRL W PEEJAY A- 033-G/094-A-15
Location: NTS: A- 033-G/094-A-15

Permit: 100040368
Facility ID: 00020579
Facility Name: CNRL PEEJAYWEST A-033-G/094-A-15 001
Facility Type: Well Facility
Location: NTS: A- 033-G/094-A-15

Authorized by BCER