Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3750
Inspection Date: 2026-11-17
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1411HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead (fresh water source) Suspended. Wellhead located in building. Signage in place at well. Pilings located around lease. MCC building out of service. No observed issues at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100079072
Well ID: 29724
Well Name: CNRL W PEEJAY B-A044-G/094-A-15
Location: NTS: B-A044-G/094-A-15

_____

Authorized by BCER