Inspection Report

Permit Holder: Harvest Operations Corp.
Inspection: 2026-3778
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:

Well pad is Active.

LEL detected from d-A23 and d-B23 surface casing vents, consistent with last test results in BCER systems (2024).

ESD compliant to standards.

Well signs compliant.

I chem tank compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100072310
Well ID: 26735
Well Name: HARVEST HZ HAY D-A023-G/094-I-09
Location: NTS: D-A023-G/094-I-09

Permit: 100072311
Well ID: 26736
Well Name: HARVEST HZ HAY D-B023-G/094-I-09
Location: NTS: D-B023-G/094-I-09

Permit: 100072310
Facility ID: 00024840
Facility Name: HARVEST HAYRIVER D-023-G/094-I-09 001
Facility Type: Well Facility
Location: NTS: D- 023-G/094-I-09

Permit: 100072311
Facility ID: 00024841
Facility Name: HARVEST HAYRIVER D-023-G/094-I-09 002
Facility Type: Well Facility
Location: NTS: D- 023-G/094-I-09

Permit: 100072875
Pipeline Project ID: 000022322
Segment IDs (Location): 1 (From NTS: D- 023-G/094-I-09 To NTS: B- 022-G/094-I-09), 2 (From NTS: D-023-G/094-I-09 To NTS: B- 022-G/094-I-09), 3 (From NTS: B- 022-G/094-I-09 To NTS: D- 023-G/094-I-09)

Permit: 100075330
Pipeline Project ID: 000022692
Segment IDs (Location): 1 (From NTS: B- 033-G/094-I-09 To NTS: D- 023-G/094-I-09), 2 (From NTS: D-023-G/094-I-09 To NTS: B- 033-G/094-I-09)

_____

Authorized by BCER