Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3785
Inspection Date: 2026-11-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1230HRS.

Access road- Frozen Access. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. Barricades in place around wellhead. Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handles not chained, locked and secure or removed (See attached). Surface casing vent flow test- No Flow detected.

Internal records indicate well facility is still active, when not other surface equipment or buildings on site.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002617
Well ID: 01977
Well Name: CNRL WEASEL B- 023-B/094-H-02
Location: NTS: B- 023-B/094-H-02

Permit: 100002617
Facility ID: 00018565
Facility Name: CNRL WEASEL B-023-B/094-H-02 001
Facility Type: Well Facility
Location: NTS: B- 023-B/094-H-02

Authorized by BCER