Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3786
Inspection Date: 2026-11-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Access opportunity inspection of surface equipment on site.

Performed inspection of location at 1247HRS.

Access road- Frozen Access. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. No barricades in place around wellhead. Signage on ground beside well broken & missing warning decal (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002183
Well ID: 01644
Well Name: CNRL WEASEL D- 013-B/094-H-02
Location: NTS: D- 013-B/094-H-02

_____

Authorized by BCER