Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3787
Inspection Date: 2026-11-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1052HRS.

Access road- Frozen Access. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- A-85-J Pumpjack & Wellhead Suspended. No barricades in place around wellhead (Limited risk due to isolated location). Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected.

A-a85-J Wellhead Suspended. No barricades in place around wellhead (Limited risk due to isolated location). Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handle not chained, locked and secure or removed (See attached). Surface casing vent flow test- No Flow detected.

Building entry test- No alarms on personal monitor. Building out of service.

Tank on site- Out of service.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100013406
Well ID: 07835
Well Name: CNRL OSPREY A- 085-J/094-A-15
Location: NTS: A- 085-J/094-A-15

Permit: 100049625
Well ID: 20043
Well Name: CNRL OSPREY A-A085-J/094-A-15
Location: NTS: A-A085-J/094-A-15

_____

Authorized by BCER