Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3788
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1325HRS.

Access road- Frozen Access No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Pumpjack & Wellhead Suspended. Barricades in place around wellhead. Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected.

Tank on site- Out of service.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100013490
Well ID: 07848
Well Name: CNRL OSPREY D- 074-J/094-A-15
Location: NTS: D- 074-J/094-A-15

_____

Authorized by BCER