Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-3791
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1359HRS.

Access road- Limited access. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment-Wellhead Abandoned. Surface equipment removed from site. Signage in place at lease entrance. Observed large hole likely where wellhead was removed (See attached). Officer spoke with company rep performing decommissioning at a different location, and the entire area is being restored.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100077241
Well ID: 28790
Well Name: STRATHCONA WEASEL D- 055-B/094-H-02
Location: NTS: D- 055-B/094-H-02

_____

Authorized by BCER