Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-3792
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1413HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment-Wellhead Abandoned. Surface equipment removed from site. No signage observed. Observed trenches in ground possibly where surface equipment was removed (See attached). Officer spoke with company rep performing decommissioning at a different location, and the entire area is being restored.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002407
Well ID: 01811
Well Name: STRATHCONA ET AL WEASEL D- 057-B/094-H-02
Location: NTS: D- 057-B/094-H-02

Permit: 100002407
Facility ID: 00018549
Facility Name: STRATHCONA WEASEL D-057-B/094-H-02 001
Facility Type: Well Facility
Location: NTS: D- 057-B/094-H-02

_____

Authorized by BCER