Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-3794
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1424HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment-Wellhead Abandoned. Surface equipment removed from site. Signage at lease entrance. Observed trenches in ground possibly where surface equipment was removed (See attached). Officer spoke with company rep performing decommissioning at a different location, and the entire area is being restored.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003780
Well ID: 02834
Well Name: STRATHCONA ET AL W WEASEL D- 071-C/094-H-02
Location: NTS: D- 071-C/094-H-02

Permit: 100003780
Facility ID: 00018615
Facility Name: STRATHCONA WEASELWEST D-071-C/094-H-02 001
Facility Type: Well Facility
Location: NTS: D- 071-C/094-H-02

_____

Authorized by BCER