# Inspection Report

Permit Holder: Strathcona Resources Ltd.
Inspection: 2026-3795
Inspection Date: 2026-11-18
Inspection Outcome: Inspected

**Inspection Comment:**
Access opportunity inspection of surface equipment on site.

Performed inspection of location at 1435HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment-Wellhead Abandoned. Surface equipment removed from site. Signage at lease entrance. Officer spoke with company rep performing decommissioning at a different location, and the entire area is being restored.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043144
Well ID: 17896
Well Name: STRATHCONA W WEASEL B- 089-B/094-H-02
Location: NTS: B- 089-B/094-H-02

_____

Authorized by BCER