Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3796
Inspection Date: 2026-11-18
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1052HRS.

Access road- Frozen Access No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Pumpjack & Wellhead Suspended. No barricades in place around wellhead (Limited risk due to isolated location). Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Polish rod removed. Surface casing vent flow test- No Flow detected.

Note: Pumpjack housing building has collapsed and damaged panels are laying in piles on ground around pumpjack and scattered around lease (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001877
Well ID: 01408
Well Name: CNRL ET AL W BEATTON D- 021-L/094-H-02
Location: NTS: D- 021-L/094-H-02

Permit: 100010749
Facility ID: 00000330
Facility Name: CNRL BEATTONRIVER D-021-L/094-H-02 001
Facility Type: Satellite Battery
Location: NTS: D- 021-L/094-H-02

Authorized by BCER