Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3811
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Inspection Overview
Site 10-26-081-16 was inspected at approximately 0000 hours. Conditions were overcast with a temperature of -9°C.

Inspection Results
• Access and signage: Access on to site is low grade. No signage present - Operator called and provided signage to the building.
• Site condition: Inactive site - gate and pipes, broken fence, some grasses
• Wellheads: removed
• Meter/separator buildings: out of service
• Chemical tanks: out of service
• Associated pipelines: Vegetation cover along the pipelines was well established.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001787
Well ID: 01355
Well Name: CANLIN ET AL PARKLAND 10-26-081-16
Location: DLS: 10-26-081-16

Permit: 100001787
Facility ID: 00018504
Facility Name: CANLIN PARKLAND 10-26-081-16 001
Facility Type: Well Facility
Location: DLS: 10-26-081-16

Permit: 100027313
Pipeline Project ID: 000008919
Segment IDs (Location): 2 (From DLS: 09-25-081-16 To DLS: 10-26-081-16)

Permit: 100062004
Pipeline Project ID: 000000093
Segment IDs (Location): 2 (From DLS: 10-26-081-16 To DLS: 16-26-081-16)

Permit Holder: Canlin Energy Corporation

Authorized by BCER