Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3813
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Site 11-28-081-16 was inspected at approximately 1200 hours. Weather conditions were overcast, with a temperature of -9°C.
The inspection included the following:
Access and signage: Low grade, gated site. Signage was clear and legible.
Site: The wellsite was clean, and dry.
Wellheads: Bull plugs, SCV, locks, and leaks were checked. No SCV flow was detected. Critical valves were locked, with no concerns noted.
Meter/separator buildings: Locks, leaks, caps, and vents were checked, with no concerns noted.
Chemical tanks: Leaks, grounds, and caps were checked, with no concerns noted.
Riser and pig stations: Chains and grounds were checked, with no concerns noted.
Associated pipelines were well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100035432
Well ID: 15379
Well Name: CANLIN ET AL PARKLAND 11-28-081-16
Location: DLS: 11-28-081-16

Permit: 100035432
Facility ID: 00020061
Facility Name: CANLIN PARKLAND 11-28-081-16 001
Facility Type: Well Facility
Location: DLS: 11-28-081-16

Permit: 100059347
Pipeline Project ID: 000019393
Segment IDs (Location): 1 (From DLS: 11-28-081-16 To DLS: 07-27-081-16), 2 (From DLS: 07-27-081-16 To DLS: 11-28-081-16)

Permit Holder: Canlin Energy Corporation

Authorized by BCER