Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3819
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1240HRS.

Access road- Vegetation growing on access road. Frozen access only. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Well: Wellhead Abandoned. Surface equipment removed from site. Legacy placard in place in approx area wellhead would have been located (See attachecd). No observed issues at time of inspection.

Note: various other inactive equipment on site, including an facility with active equipment (according to internal records).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100005213
Well ID: 03722
Well Name: CNRL DAHL A- 089-H/094-H-07
Location: NTS: A- 089-H/094-H-07

_____

Authorized by BCER