Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3822
Inspection Date: 2026-11-23
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Access opportunity inspection of surface equipment on site.

Performed inspection of location at 1307HRS.

Access road- Vegetation growing on access road. Frozen Access Only. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. No barricades in place around wellhead (Limited risk due to isolated location). No observed signage at lease entrance or around wellhead. Positive isolation maintained (flow lines removed). Valve Handles not chained, locked and secure or removed (See attached). Surface casing vent flow test- No Flow detected.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks on site- Chemical tank has unknown product remaining (See attached). No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100050103
Well ID: 20021
Well Name: CNRL DAHL C- 077-H/094-H-07
Location: NTS: C- 077-H/094-H-07

_____

Authorized by BCER