Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3825
Inspection Date: 2026-11-23
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:
Access opportunity inspection of surface equipment on site.

Performed inspection of location at 1534HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. Barricades in place at entrance. Signage in place at well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Needle valve leaking unknown substance from handle onto ground (see attached). Surface casing vent flow test- No Flow detected.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000688
Well ID: 00538
Well Name: CNRL W BEATTON D- 038-K/094-H-02
Location: NTS: D- 038-K/094-H-02

_____

Authorized by BCER