Inspection Report

Permit Holder: Aduro Resources Ltd.
Inspection: 2026-3835
Inspection Date: 2026-11-23
Inspection Outcome: Inspected

Inspection Comment:
Signage no concerns

SCV's no venting observed.'

Both wellheads isolated and chained.

Site not in operation.

No other concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040834
Well ID: 16537
Well Name: ADU MONIAS 03-18-082-22
Location: DLS: 03-18-082-22

Permit: 100055434
Well ID: 21493
Well Name: ADU MONIAS A03-18-082-22
Location: DLS: A03-18-082-22

Permit: 100055434
Facility ID: 00022256
Facility Name: ADU MONIAS 03-18-082-22 002
Facility Type: Well Facility
Location: DLS: 03-18-082-22

Authorized by BCER